

# **STRIPE-OFF™**

**Striping Paint Overspray Release**

## **Application Tip Sheet**

Start with a clean surface.

Then simply apply an even coat of **STRIPE-OFF™** onto any surface where you typically get paint overspray (outrigger, gun packs, tires, stencils, etc.).

Go out and stripe as normal.

Come back and pressure wash area you applied **STRIPE-OFF™** to and watch overspray come right off.

Re-apply **STRIPE-OFF™** after pressure washing.

**CALL TOLL FREE TO REORDER**



[solutions@rhomar.com](mailto:solutions@rhomar.com)  
[www.rhomar.com](http://www.rhomar.com)

2107 E Rockhurst St • Springfield, MO 65802

**1-800-688-6221**

417-866-5592